



1/23




FIG. 1A




FIG. 1B

$$p(x) = x^{42} + x^{35} + x^{33} + x^{27} + x^{26} + x^{25} + x^{22} + x^{21} + x^{19} + x^{18} + x^{17} + x^{16} + x^{10} + x^7 + x^6 + x^5 + x^3 + x^2 + x^1 + 1$$

250

FIG. 2A




FIG. 2B




FIG. 3





FIG. 4A



5/23

FIG. 4B




FIG. 5

7/23




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9




FIG. 10




FIG. 11A

i Available Bits




FIG. 11B




FIG. 12




FIG. 13




FIG. 14

17/23




FIG. 15




FIG. 16




FIG. 17

20/23




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22